

SAFETY NOTICE N0 24 - 01

To: All skydivers
Subject: Fluid Wings 400lb suspension line.
Compliance: Compulsory
Date of Issue: 15 March 2024
Compliance due: Before next jump

This Safety Notice is issued following a notice by the manufacturer (Document 24-400-001) dated 12 March 2024.

Background:

After a recent fatality at Skydive Dubai, Fluid Wings has just released a Mandatory Maintenance Inspection notice, effective immediately.

All Fluid wings Parachutes with **400lb.** suspension line **must** be evaluated and confirmed as airworthy as per the notice **before** your next jump.

[Fluid Wings Notice](#)

The NZPIA strongly recommends that all high-performance canopies with 300 – 400lb. suspension lines be inspected before their next jump as a precaution. Although the notice came from Fluid Wings, the underlying issue is not limited to the specific line they use.

If you are unsure of the line type on your canopy, speak to your local Parachute Technician or DZSO for clarification.



David du Plessis
CHIEF EXECUTIVE OFFICER
NEW ZEALAND PARACHUTE INDUSTRY ASSOCIATION (NZPIA)